INSPECTION REPORT

PERMIT NUMBER:	BP-13-00742	OWNER'S NAME:	ROSENBERRY
DATE:	12/3/2014	TYPE:	Insulation
TIME STARTED:	11:40 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-16-14000-0007		
1. insulat	ion ok		
2. fix leak	king p trap in laundry roo	m wall	
INCERNICATIONS fire	lank than aluta anyon		
INSTRUCTIONS: 11X	leak, then ok to cover		
NEXT INSPECTION:	final		
RE-INSPECTION FEE	DUE? NO YES		\$
·	UIRED, RE-INSPECTION FEES MUST BE		
QUI	ESTIONS? PLEASE CONTACT THE INSPE		
jessica.contratto @co.kittitas.wa.us			
	TION REQUEST LINE: <u>www.co.kitt</u>i 1 N. Ruby Street, Suite 2, Ellensburg, V		