INSPECTION REPORT

PERMIT NUMBER:	BP-13-00742	OWNER'S NAME:	ROSENBERRY	
DATE:	5/27/2015	TYPE:	Final	
TIME STARTED:	10:21 AM	INSPECTOR:	Justin Bennett	
MAP NUMBER:	20-16-14000-0007			
1. Blower O	k			
2. Plumbing Final Ok				
3. Mechanical Final Ok				
4. Access approved				
5. Septic Approved				
6. Energy C	6. Energy Credits Ok			
7. Fireplace rough in Ok				
8. Fireplace not functioning - Verify operation				
9. Complete fire seperation in the Attic/Feed area @ fire wall				
INSTRUCTIONS: Complete fire seperation & verify fireplace operation/Re-inspection				
NEXT INSPECTION: Re-inspection				
RE-INSPECTION FEE I	DUE? NO YES		\$	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
<u>iustin.bennett</u> @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 				