INSPECTION REPORT

PERMIT NUMBER: BP-13-00800 OWNER'S NAME: HILL

DATE: TIME STARTED:		6/30/2014 11:12 AM		1	ГҮРЕ:	Final
				I	NSPECTOR:	
INSTR	UCTIONS: Se	al all duct penetration	s in floor and attic, in	cluding existing. Fini	sh fire sealing at furnace	area to attic. Complete range vent. send pictures when completed
NEXT	INSPECTION:					
RE-INS	SPECTION FEE	DUE?	✓ NO	YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION						
		QUESTIONS ADDRESS:	S? PLEASE CON	NTACT THE IN:	SPECTOR AT THE	FOLLOWING E-MAIL _@co.kittitas.wa.us
	• INSPE	CTION REQU	EST LINE: ww	w.co.kittita	s.wa.us/cds/re	equest.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506