

KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-13-00813	OWNER'S NAME:	BARBER
DATE:	6/4/2015	TYPE:	Mechanical
TIME STARTED:	4:07 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-32030-0003		

1. remove insulation from between chimney and structure to maintain 1" clearance to com	bus
tibles	
INSTRUCTIONS: complete above	
NEXT INSPECTION: re-inspect	
RE-INSPECTION FEE DUE? V YES \$	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION	
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:	
iessica.contratto @co.kittitas.wa.us	
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 	