## **INSPECTION REPORT**

PERMIT NUMBER: BP-13-00813 OWNER'S NAME: BARBER

DATE:	6/8/2015	TYPE:	Re-inspection
TIME STARTED:	12:07 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-32030-0003		
1. chimney	clearances ok on exterior		
		istibles with finish m	naterials. Non combustibles may
C	ontact		
NEXT INSPECTION:	final chimney		
RE-INSPECTION FEE	E DUE? NO	YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
	ie	essica.contratto @co	o.kittitas.wa.us
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			