## **INSPECTION REPORT**

**PERMIT NUMBER:** 

BP-14-00049

OWNER'S NAME:

**HAYDEN** 

DATE:		10/2/2014	TYPE:	Multiple (see notes)	
TIME STARTED:		2:54 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		17-19-06020-000	2		
	1. CS16 straps over blocking ok				
INISTRI	ICTIONS: O	k to cover roof			
INSTRUCTIONS: ok to cover roof					
NEVE	NCDECTION				
NEXT INSPECTION: frame/plumb/mech					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION  QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •					
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					