INSPECTION REPORT

PERMIT NUMBER:	BP-14-00049	OWNER'S NAME:	VALLEY VET
DATE:	11/6/2014	TYPE:	Frame-Plumb-Mech
TIME STARTED:	10:58 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-06020-0002		
1. DWV a	 at 6#/15-ok		
2. H2O a	t 100#/15-ok		
3. gas at 25#/15-ok			
4. nail plates where needed			
5. draftstop ok			
	<u> </u>		
INSTRUCTIONS: ok to insulate pending L&I approval			
NEXT INSPECTION:	oxygen/gas systems, insulation		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
	TION REQUEST LINE: www.co.kitti L N. Ruby Street, Suite 2, Ellensburg, V		