INSPECTION REPORT

PERMIT NUMBER	^{::} BP-14-00049	OWNER'S NAME:	HAYDEN
DATE:	12/29/2014	TYPE:	Re-inspection
TIME STARTED:	11:23 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-06020-0002		
1. fire c	aulk and seal in gas close	et	
2. landing at rear exterior man door			
3. provide adequate combustion air for water heater			
4. L&I final needs approval			
5. complete med gas certification			
6. secure fire marshal signatures or confirmation			
INSTRUCTIONS: complete above, call for re-final			
NEVT INSPECTION			
NEXT INSPECTION	· final		
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
	ECTION RECITES LINE WWW. CO KIT	ITAS WA HS/CAS/PANH	PST 25M OF 5114-46/-/644 A

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506