KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-14-00095	**OWNER'S NAME:**	TILTON
DATE:	10/7/2014	**TYPE:**	Insulation
TIME STARTED:	11:16 AM	**INSPECTOR:**	Jessica Contratto
MAP NUMBER:	17-19-02077-0003		

	1. no backing behind shower flange in mud room. not nailed
	2. tub not attached to wall
	3. R-21 not PROPERLY installed behind shower in hall bath
	4. staple insulation to stud faces in garage

INSTRUCTIONS: Fix insulation properly. Staple in garage. Do Not Cover. Pay re-inspection fee

NEXT INSPECTION: re-inspect

RE-INSPECTION FEE DUE? ☐ **NO** ☑ **YES** **$** 65.00

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

jessica.contratto **@co.kittitas.wa.us**