## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00095	OWNER'S NAME:	TILTON
DATE:	10/13/2014	TYPE:	Re-inspection
TIME STARTED:	1:48 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-02077-0003		
1. insulat	ion corrections ok		
2. put vapor barrier over unfaced insulation in garage			
INSTRUCTIONS: complete above, ok to cover			
NEXT INSPECTION: f	inal		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
- INICECO		ca.contratto @co.ki	
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>			