## **INSPECTION REPORT**

BP-14-00173

**PERMIT NUMBER:** 

OWNER'S NAME: THE PASS LLC

DATE:		10/7/2014	TYPE:	Exterior shear
TIME STARTED:		1:06 PM	INSPECTOR:	Amber Green
MAP NUMBER:		22-11-04055-003	32	
1. 3X sill plate missing at P2 shearwalls - obtain engineers approval/fix.				
INSTRUCTIONS: OK TO COVER EXTERIOR.				
NEXT INSPECTION: FRAME/PLUMB/MECH				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
amber.green @co.kittitas.wa.us				
<ul> <li>INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506</li> </ul>				
.11 11 11day 50 600 50100 1/ 110110001 6/ 11/130310 - 11/011 01/100 11/01 303 301 7300				