INSPECTION REPORT

TYPE:

OWNER'S NAME: CORBURN

Rough-in mechanical

PERMIT NUMBER: BP-14-00216

DATE:

11/4/2015

TIME STARTED:	3:17 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	21-14-34059-0001		
1. Draftsto	pp at updtairs fireplace does	s not meet clearances f	rom chimney
2. Gas line not on test			
3. Exhaust duct ok			
4. Supply duct ok			
	Address corrections. Also sadded windows in shearwal		at framing ans engineering for
NEXT INSPECTION	: Framing		
RE-INSPECTION FE	E DUE? V NO	YES	\$
	QUIRED, RE-INSPECTION FEES N		
Q	UESTIONS? PLEASE CONTACT TH		
		iessica.contratto @co	
	ECTION REQUEST LINE: <u>www.</u> I11 N. Ruby Street, Suite 2, Ellen:		