INSPECTION REPORT

OWNER'S NAME: MARTIN

BP-14-00249

PERMIT NUMBER:

DATE:		8/1/2014	TYPE:	Insulation	
TIME STARTED:		11:00am	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		17-18-05050-0002			
i	insulatio	ulation ok			
INSTRUCTIONS: ok to cover garage remodel					
NEXT INSPECTION: final in garage					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
	QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: jessica.contratto @co.kittitas.wa.us				
		CTION REQUEST LINE: www.co.kitt 1 N. Ruby Street, Suite 2, Ellensburg, N			
·			·		