INSPECTION REPORT

PERMIT NUMBER:	BP-14-00261	OWNER'S NAME:	VAN DEVENTER
DATE:	9/4/2014	TYPE:	Insulation
TIME STARTED:	10:46 AM	INSPECTOR:	Amber Green
MAP NUMBER:	19-16-02000-0006		
1. Framir	ng Corrections OK		
2. Complete sheathing on interior at portal frame fix.			
3. Obtain fire sprinkler inspection and approval.			
INSTRUCTIONS: Complete above, then OK TO COVER.			
NEXT INSPECTION: Interior Sheathing			
RE-INSPECTION FEE I	DUE? NO YES	i	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			