INSPECTION REPORT

PERMIT NUMBER:	BP-14-00279	OWNER'S NAME:	COONS
DATE:	9/19/2014	TYPE:	Final
TIME STARTED:	11:51 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-16-34061-0014		
1. Blower	door results not posted.	Was test perfe	ormed?
2. Need to meet 1.5 energy credits			
3. provide 36"x36" landings at exterior doors where more than 7.25" to grade.			
INSTRUCTIONS: complete above, call for re-inspection			
NEXT INSPECTION:	e-inspection		
RE-INSPECTION FEE I	OUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			