INSPECTION REPORT

BP-14-00301

PERMIT NUMBER:

OWNER'S NAME: SUNRIDGE RANCH II

DATE:	11/6/2014	TYPE:	Frame-Plumb-Mech	
TIME STARTED	: 1:41 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:	16-19-12000-0	010		
1. H20	O at 67#/15-ok			
2. gas at 30#/15-ok				
3. install draftstop at fireplace				
4. atta	ach FSK paper behind	d fireplace		
5. DV	W at 5#/ 15- ok			
6. trus	ss brace at A13			
INSTRUCTIONS	: ok to insulate			
NEXT INSPECTION	ON: insulation			
RE-INSPECTION	FEE DUE? NO	YES	\$	
IF	REQUIRED, RE-INSPECTION FEES	MUST BE PAID PRIOR TO SC	HEDULING A RE-INSPECTION	
	QUESTIONS? PLEASE CONTACT	THE INSPECTOR AT THE FOLL	OWING E-MAIL ADDRESS:	
		jessica.contratto @co	o.kittitas.wa.us	
• IN:	SPECTION REQUEST LINE: www	w.co.kittitas.wa.us/cds/re	quest.asp or 509-962-7694 ◆	

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506