INSPECTION REPORT

TYPE:

PERMIT NUMBER:

DATE:

BP-14-00377

11/5/2014

OWNER'S NAME: FOX

Shearwalls

TIME STARTED:	10:40 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-17-01000-0033		
1. exterior shear ok			
INSTRUCTIONS: 0	ok to cover		
NEXT INSPECTION	framing/final		
RE-INSPECTION FE	E DUE? NO YE	S	\$
IF RE	QUIRED, RE-INSPECTION FEES MUST B	E PAID PRIOR TO SO	CHEDULING A RE-INSPECTION
0	UESTIONS? PLEASE CONTACT THE INSP	PECTOR AT THE FOLI	LOWING E-MAIL ADDRESS:
	jess	sica.contratto @c	o.kittitas.wa.us
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			