## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00382	OWNER'S NAME:	BRAIN
DATE:	1/20/2015	TYPE:	Final
TIME STARTED:	10:48 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-18-36111-0002		
1. seal around dryer vent at foundation			
2. seal penetrations in garage ceiling			
INSTRUCTIONS: complete above, final ok			
	<u> </u>		
NEXT INSPECTION: N/A			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:  jessica.contratto @co.kittitas.wa.us			
INSPECTION REQUEST LINE: <a href="https://www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 •			
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			