INSPECTION REPORT

PERMIT NUMBER:	BP-14-00428	OWNER'S NAME:	BUSHNELL
DATE:	1/8/2015	TYPE:	Frame-Plumb-Mech
TIME STARTED:	10:06 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-13050-0004		
1. plumb	ping not on test		
-	lips at 12"oc per 3/s4		
3. dryer vent not connected below floor			
4. plumbing and electrical in unfinished basement. speak with plan reviewer about options			
5. 1000lb straps to header per portal frame detail2/s5			
INSTRUCTIONS: see plumbing on test before insulation, complete above			
NEXT INSPECTION:	re-plumb		
RE-INSPECTION FEE	DUE? NO YES	}	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506