INSPECTION REPORT

PERMIT NUMBER:	BP-14-00437	OWNER'S NAME:	HELGESON
DATE:	2/23/2015	TYPE:	Final
TIME STARTED:	12:58 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-15-08050-0004		
1. Blower door test does not meet code requirements of			
2. Rangehood not installed			
3. 36" length landing required at egress doors			
4. kitchen sink not functioning			
5. seal penetration in garage ceiling around ductwork			
6. no attic access cover in garage			
7. obtain sewer and access approval on permit card			
8. bollards not installed in garage for furnace/water heater protection			
INSTRUCTIONS: complete above, call for re-inspection			
NEXT INSPECTION: re-inspection			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
justin.bennett @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			