## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00512	OWNER'S NAME:	RODRIGUEZ
DATE:	8/4/2014	TYPE:	Final
TIME STARTED:		INSPECTOR:	Amber Green
MAP NUMBER:	18-18-19050-0001		
Provide duct leakage test results.			
2. Provide bollard in garage for mechanical protection.			
3. Obtain Labor & Industries inspection approval.			
4. Complete insulation at main trunk line.			
INSTRUCTIONS: Complete above, re-call inspection.			
	· · · · · · · · · · · · · · · · · · ·		
NEXT INSPECTION: Re-inspection			
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •			