INSPECTION REPORT

PERMIT NUMBER:	BP-14-00516	OWNER'S NAME:	GRANGER
DATE:	10/21/2014	TYPE:	Foundation walls
TIME STARTED:	3:02 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-19051-0037		
1. ok to p	our		
2. add 2 v	vents		
INSTRUCTIONS: ok	to pour.		
NEXT INSPECTION:	retro footings		
RE-INSPECTION FEE I	DUE? NO YES		\$
	UIRED, RE-INSPECTION FEES MUST BE		
QUI	ESTIONS? PLEASE CONTACT THE INSPI iess	ector at the follow ica.contratto @co.k i	
• INSPEC	TION REQUEST LINE: www.co.kitt		
	1 N. Ruby Street, Suite 2, Ellensburg, V		