INSPECTION REPORT

OWNER'S NAME: ELY

PERMIT NUMBER:	BP-14-00531	OWNER'S NAME:	ELY
DATE:	2/24/2015	TYPE:	Mechanical and plumbing
TIME STARTED:	1:16 PM	INSPECTOR:	Amber Green
MAP NUMBER:	20-15-29051-0075		
1. Insulat	ion behind showers - ins	ulate, single va	apor barrier.
2. H2O (80#/15min) - OK			
3. DWV (5#/15min) - OK			
4. Gasline (30#/15min) - OK			
INSTRUCTIONS: Complete #1.			
NEXT INSPECTION:	Framing		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
	amber.green @co.kittitas.wa.us		
	TION REQUEST LINE: www.co.kitti		