INSPECTION REPORT

TYPE:

PERMIT NUMBER:

DATE:

BP-14-00536

10/28/2014

OWNER'S NAME: WADDELL

Exterior shear

TIME STARTED:	3:42 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-06098-0003		
1. exterior shear ok			
INSTRUCTIONS: ok to cover			
NEXT INSPECTION: framing/plumb/mech			
RE-INSPECTION	FEE DUE? NO YE	S	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 			