INSPECTION REPORT

PERMIT NUMBER:	BP-14-00537	OWNER'S NAME:	PITTS
DATE:	12/18/2014	TYPE:	Shearwalls
TIME STARTED:	2:15 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-29051-0092		
1. CS16	strap at bedroom 2 upsta	airs. Circled on	plan
2. interior shear ok			
3. exterior shear ok			
INSTRUCTIONS: complete above, see at framing			
NEXT INSPECTION:	framing/plumb/mech		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
	TION REQUEST LINE: www.co.kitt 1 N. Ruby Street, Suite 2, Ellensburg, V		