INSPECTION REPORT

PERIVITI NUIVIBER:	BP-14-00537	OWNER'S NAIVIE:	PHIS
DATE:	2/24/2015	TYPE:	Re-inspection
TIME STARTED:	12:48 PM	INSPECTOR:	Amber Green
MAP NUMBER:	20-15-29051-0092		
1. Gaslin	e (17#/15min) - OK		
2. Add up	olift clips at rafter to bea	ım connection a	t rear porch.
3. DWV ((H20/15min) - OK		
4. Other	corrections OK		
INSTRUCTIONS: O	K to Insulate. Contractor will e	-mail photo of clips.	
NEXT INSPECTION:	Insulation		
RE-INSPECTION FEE	DUE? NO YI	ES	\$
IF REQ	UIRED, RE-INSPECTION FEES MUST	BE PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QU	ESTIONS? PLEASE CONTACT THE INS	_	
amber.green @co.kittitas.wa.us			
	TION REQUEST LINE: <u>www.co.ki</u> t 1 N. Ruby Street, Suite 2, Ellensburg,		