INSPECTION REPORT

PERMIT NUMBER:		BP-14-00561	OWNER'S NAME:	AUVIL FRUIT
DATE:		10/17/2014	TYPE:	Final
TIME STARTED:		10:13	INSPECTOR:	Lou Whitford
MAP NUMBER:		15-23-09000-0005		
	1. HANDRA	IL AT BOTH STAIRS IS INCOR	RECT. MUST BE	LOCATED BETWEEN 34"-38".
	2. ONLY ONE SIDE OF EACH STAIR NEEDS TO COMPLY.			
	3. MEASURE FROM THE TOE OF STAIR TO TOP OF HANDRAIL FOR CORRECT HEIGHT			
INSTRUCTIONS:				
NEXT INSPECTION: RE-INSPECT HANDRAIL. LIFE SAFETY ISSUE				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
	lou.whitford @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 				