INSPECTION REPORT

PERIVITI NUIVIBER:	BP-14-00702	OWNER'S NAIVIE:	OLSON
DATE:	11/10/2014	TYPE:	Mono pour
TIME STARTED:	4:07 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	21-17-36091-0042		
1. ok to p	our footings		
2. (2) #4 bars in each 24x24 interior pad			
INSTRUCTIONS: ok to pour			
NEXT INSPECTION:	final		
RE-INSPECTION FEE	DUE? NO YES	i	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: jessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			