INSPECTION REPORT

PERMIT NUMBER:	BP-14-00709	OWNER'S NAME:	CASCADE VIEW
DATE:	3/25/2015	TYPE:	Insulation
TIME STARTED:	9:56 AM	INSPECTOR:	Amber Green
MAP NUMBER:	18-18-27071-0144		
1. Will se	e fresh air supply ducted	I to air handler	at final inspection.
2. Other corrections OK			
3. Insulation OK			
INSTRUCTIONS: OF	K to Cover		
NEXT INSPECTION:	Final		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
	amber.green @co.kittitas.wa.us		
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 			