## **INSPECTION REPORT**

BP-14-00711

**PERMIT NUMBER:** 

OWNER'S NAME: MUNNOCH

DATE:		12/30/2014	TYPE:	Final	
TIME STARTED:		3:22 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		19-16-24010-0005			
	1. fireplace fresh air/clearances ok				
INSTRUCTIONS: final ok					
NEXT INSPECTION: N/A					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •					
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506					