INSPECTION REPORT

BP-14-00767

PERMIT NUMBER:

OWNER'S NAME: DUNCAN

DATE:		11/19/2014	TYPE:	Gas piping
TIME STARTED:		10:34 AM	INSPECTOR:	Amber Green
MAP NUMBER:		18-17-36050-0004		
	1. Gas Piping (20#/15min) - ok			
	2. Complete furnace install.			
	3. Install sniffer alarm.			
	4. Complete duct leakage test.			
INSTRUCTIONS: Complete #2 - #3, then call for final inspection.				
NEXT INSPECTION: Final				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
	amber.green @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 				