INSPECTION REPORT

PERMIT NUMBER:

BP-14-00776

OWNER'S NAME: ZELLMER

DATE:		3/24/2015	TYPE:	Final	
TIME STARTED:		12:54 PM	INSPECTOR:	Justin Bennett	
MAP NUMBER:		19-17-23050-0027			
	1. Attatchment Detail of I Beam to Ecology Block Not per RTR Engineer Page 8 of 8.				
	2. Reflectors Not Installed at 3-4 Per Fire Marshall Letter 06/23/2014.				
INSTRUCTIONS: Provide Engineering for Alternate Attatchment Method Used. Install Reflectors.					
NEXT INSPECTION: Re-inspection					
RE-INSPECTION FEE DUE? NO YES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	justin.bennett @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					
+11 N. Nuby Street, Suite 2, Literisburg, WA 30320 Vividiti Office Little. 303-302-7300					