INSPECTION REPORT

PERMIT NUMBER:	BP-14-00785	OWNER'S NAME:	BACK COUNTRY
DATE:	9/4/2015	TYPE:	Framing
TIME STARTED:	1:21 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-15-07060-0011		
1. garage fra	aming/trusses ok		
2. gas not on test			
3. draftstop upstairs in chase			
4. house trusses ok			
5. permit card not on site			
INSTRUCTIONS: ok to insulate. See gas pipe on test			
NEXT INSPECTION: insulation			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 			