INSPECTION REPORT

PERMIT NUMBER:		BP-14-00830	OWNER'S NAME:	SEUBERT	
DATE:		6/16/2015	TYPE:	Final	
TIME STARTED:		10:30 AM	INSPECTOR:	Justin Bennett	
MAP NUMBER:		17-20-04051-0004			
	1. Complete	range vent installation			
	2. Complete crawl insulation/Insulation certificate				
	3. Complete light install in bedroom				
	4. Complete fire seperation @ water heater				
	5. L&I complete				
	6. Provide Blower door results				
	7. Provide access permit approval				
	8. Provide septic approval				
	9. Smoke/CO detectors Ok				
INSTRUCTIONS: Complete items above/Re-inspection					
NEXT INSPECTION: Re-Inspection					
RE-INSPECTION FEE DUE? V NO YES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iustin.bennett @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					