INSPECTION REPORT

TYPE:

INSPECTOR:

BP-14-00833

12/30/2014

10:12 AM

PERMIT NUMBER:

TIME STARTED:

DATE:

OWNER'S NAME: WILLOWBROOK FARMS II LLC

Gas piping

Jessica Contratto

MAP N	IUMBER:	18-17	-14040-(0005			
1. gas at 30#/15 - ok							
INSTRUCTIONS: ok to hook up gas. clearances on install ok. Final ok							
NEXT	INSPECTION:	N/A					
RE-IN:	SPECTION FEE	DUE?	✓ NO	YES		\$	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION							
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:							
	jessica.contratto @co.kittitas.wa.us						
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506							