INSPECTION REPORT

BP-15-00019

PERMIT NUMBER:

OWNER'S NAME: HARRISON

DATE:		4/13/2015	TYPE:	Floor framing	
TIME STARTED:		1:10 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		19-18-28000-0030			
	1. floor framing ok				
	2. Note- 3X or (2)2X sill plate at p1-3 walls at garage opening				
INSTRUCTIONS: ok to cover					
NEXT INSPECTION: shearwalls					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •					