INSPECTION REPORT

INST ECTION KET OKT			
PERMIT NUMBER:	BP-15-00156	OWNER'S NAME:	CARBARY
DATE:	2/12/2016	TYPE:	Insulation
TIME STARTED:	10:19 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-14-24050-0316		
 Insulation Ok Ok to cover areas that do not obstruct Fireplace rough-in Range hood correction not complete (submittal to be emailed) Mechanical Room revision not complete (to be emailed) Fireplaces not installed Other corrections Ok 			
INSTRUCTIONS: Ok to cover areas that will not obstruct Fireplace inspection/Complete outstanding corrections			
NEXT INSPECTION: Fireplace/Re-Inspection			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS:iustin.bennett @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506