INSPECTION REPORT

PERMIT NUMBER:	BP-15-00156	OWNER'S NAME:	CARBARY
DATE:	5/26/2016	TYPE:	Mechanical
TIME STARTED:	11:02 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-14-24050-0316		
 Downstairs Fireplace rough in Ok Ok to cover downstairs fireplace NOTE: Range Hood capacity needs to be verified - MA required NOTE: Revision for Mechanical Room outstanding 			
INSTRUCTIONS: Ok to cover downstairs fireplace/Verify Range Hood capacity and Mech. Rm @ Final			
NEXT INSPECTION: Final			
NEXT INSPECTION: Final			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>justin.bennett</u> @co.kittitas.wa.us			
INSPECTION REQUEST LINE: 509-962-7694			

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506