## **INSPECTION REPORT**

PERMIT NUMBER: BP-15-00165

12/3/2015

DATE:

OWNER'S NAME: BV RESORT HOMES

TYPE: Exterior shear

TIME STARTED	o: 4:52 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER	e: 20-15-19051-0032		
1. Exterior nailing ok			
2. One hold down missing at hall in garage entry			
3. See A35 clips to blocking at framing			
INSTRUCTIONS: Ok to cover exterior			
NEXT INSPECTION: plumb/mech			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			