## **INSPECTION REPORT**

PERMIT NUMBER:	BP-15-00167	OWNER'S NAME:	MCINTOSH
DATE:	3/30/2015	TYPE:	Mechanical
TIME STARTED:	11:38 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	18-18-08020-0003		
1. HVAC	installation Ok		
2. Conde	nsing unit installation Ok	(	
3. Final C	)k		
INSTRUCTIONS: Fir	nal Ok		
NEXT INSPECTION:	N/A		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUI	ESTIONS? PLEASE CONTACT THE INSPE		
	ju	ıstin.bennett @co.k	ittitas.wa.us
	<b>TION REQUEST LINE: <u>www.co.kitt</u>i</b> 1 N. Ruby Street, Suite 2, Ellensburg, V		