INSPECTION REPORT

PERMIT	Γ NUMBER:	BP-15-00203	OWNER'S NAME:	STRINGFELLOW	
DATE:		12/23/2015	TYPE:	Final	
TIME STARTED:		11:40 AM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-17-32057-0002			
	1. Access no	ot approved			
	2. Bollard needed in garage for mechanical equipment protection				
	3. Install smoke detector in garage				
	4. WUIC inspection by fire marshal needs completed				
	5. Woodstove will not be installed at this time. Chimney rough in and fresh air sleeve ok.				
	Will need separate permit and inspection when installed if this permit is finaled before				
	installation				
	6. Blower door test ok				
INSTRUCTIONS: Complete access approval and WUIC final. Call for re-inspection after					
NEXT INSPECTION: Do increation					
Re-inspection					
RE-INSPECTION FEE DUE? YES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					