## **INSPECTION REPORT**

TYPE:

**OWNER'S NAME:** 

**PERMIT NUMBER:** 

DATE:

BP-15-00210

4/13/2015

**CLAVICLE III LLC** 

Stove or fireplace

TIME STARTED:		4:11 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:		19-17-01000-0005		
	4 N ( D			
	1. Not Ready for Inspection.			
	2. Fireplace Framing Not Complete.			
	3. Gas Line and Gas Shutoff Valve Not Adequately Supported.			
INSTRUCTIONS: Make Corrections Above.				
NEXT INSPECTION: Re-Inspect				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
jeremy.haberman @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				