INSPECTION REPORT

| IIIOI ECITORI NEI ORI | | | |
|---|---|--------------------|------------------------------|
| PERMIT NUMBER: | BP-15-00217 | OWNER'S NAME: | ANDERSON |
| DATE: | 2/8/2016 | TYPE: | Insulation |
| TIME STARTED: | 11:36 AM | INSPECTOR: | Jessica Contratto |
| MAP NUMBER: | 19-20-35000-0001 | | |
| See crawl duction of the control of the contro | et fix at final pugh in ok. Verify exterior termina | tion at final | |
| INSTRUCTIONS: O | Final | | |
| RE-INSPECTION FEE | | PAID PRIOR TO SCHE | \$ DULING A RE-INSPECTION |
| OLIESTIONS 2 DIEASE CONTACT THE INSPECTOR AT THE FOLLOWING E MAIL | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: iessica.contratto @co.kittitas.wa.us | | | |
| | , | <u> </u> | |

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506