## **INSPECTION REPORT**

PERMIT NUMBER:	BP-15-00240	OWNER'S NAME:	LAHAIE
DATE:	4/7/2016	TYPE:	Final
TIME STARTED:	1:23 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-18-07058-0004		
<ol> <li>Blower door ok</li> <li>Plumbing ok</li> <li>Access and septic ok</li> <li>Garage separation ok</li> <li>Install P-traps on coils in attic</li> <li>Fresh air systems installed</li> <li>Energy credits ok</li> <li>complete fire marshal WUIC final</li> </ol>			
INSTRUCTIONS: complete above needed corrections. Take pics of traps installed			
NEXT INSPECTION: N/A			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506