KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00261	**OWNER'S NAME:**	BURNSTEAD
DATE:	9/24/2015	**TYPE:**	Exterior shear
TIME STARTED:	2:26 PM	**INSPECTOR:**	Jessica Contratto
MAP NUMBER:	20-15-20059-0013		

	1. HTT5 beside fireplace missing main floor
	2. exterior straps ok
	3. exterior nailing ok
	4. strap header to trimmer where hold downs are attached to single full height stud at win
	dows

INSTRUCTIONS: complete above, see by framing

NEXT INSPECTION: plumb/mech

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

jessica.contratto **@co.kittitas.wa.us**