## **INSPECTION REPORT**

PERMIT NUMBER:	BP-15-00300	OWNER'S NAME:	CLE ELUM ROSLYN SCHOOL
DATE:	8/12/2015	TYPE:	Slab plumbing
TIME STARTED:	12:55 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-21030-0013		
1. DWV o	on stack-ok		
2. slab in	sulation on stemwalls-ok	,	
INSTRUCTIONS: OK	to cover		
NEXT INSPECTION:	slab insulation/hydronics		
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUI	ESTIONS? PLEASE CONTACT THE INSPE iessi	ECTOR AT THE FOLLOW ca.contratto @co.ki	
• INSPEC		-	
<ul> <li>INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506</li> </ul>			