INSPECTION REPORT

PERMIT NUMBER:	BP-15-00300	OWNER'S NAME:	CLE ELUM ROSLYN SI
DATE:	11/5/2015	TYPE:	Framing
TIME STARTED:	4:01 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	20-15-21030-0013		
Mech OK to Cover Remaining Duct Work to be Seen at Final.			
2. 5 1/8 x 18 Glulam at Connection to to Steel "Seat Cut" to Accomodate Smaller Hanger. Pr			
ovide Engineers OK.			
3. All Other Framing OK.			
4. All Interior Shear and Exterior Shear OK.			
INSTRUCTIONS: SEnd Enginners OK and Welding Special Inspections. OK to Insulate.			
		<u> </u>	
NEVT INCRECTION.			
NEXT INSPECTION: Insulation.			
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
ieremv.haberman @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 • 411 N. Ruby Street, Suite 2. Ellensburg, WA 98926 • Main Office Line: 509-962-7506			