INSPECTION REPORT

PERMIT NUMBER: BP-15-00300 OWNER'S NAME: CLE ELUM ROSLYN SI

DATE:		11/12/2	015	TYPE:	Insulation	
TIME STARTED:		11:37 A	М	INSPECTOR	: Jessica Contra	tto
MAP NUMBER:		20-15-2	1030-0013			
	Remaining wall insulation ok					
	2. Sound wall insulation ok					
	3. Vapor barrier on prior inspected insulation verified via pictures on site					
INSTRUCTIONS: ok to cover						
NEXT INSPECTION:						
RE-INS	PECTION FEE	DUE?	✓ NO	YES	\$	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION						
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:						
	iessica.contratto @co.kittitas.wa.us					
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 •						
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506						