



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-15-00353

OWNER'S NAME: SCARSELLA

DATE: 6/8/2017

TYPE: Radiant heat

TIME STARTED: 9:45 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 20-14-24050-0214

1. Hydronics at 100# on front entry area
2. Slab insulation and vapor barrier installed
3. Note that fireplace corrections still stand
4. Exterior nailing corrections verified. Hold downs at front door not installed yet

INSTRUCTIONS: Ok to pour

NEXT INSPECTION: Plumb/mech

RE-INSPECTION FEE DUE?



NO



YES

\$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  
ADDRESS: \_\_\_\_\_ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

**INSPECTION REQUEST LINE: 509-962-7694**

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506