## **INSPECTION REPORT**

TYPE:

OWNER'S NAME: FORTUNE CREEK LLC

Rough-in mechanical

BP-15-00387

10/29/2015

PERMIT NUMBER:

DATE:

TIME STARTED:	9:51 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-15-07061-0031		
1. Gas r	not on sufficient pressure, 15#	min	
	ust duct ok		
	lace rough in ok		
-	<u> </u>		
INSTRUCTIONS:	See gas on test by framing		
NEXT INSPECTIO	<sup>DN:</sup> Framing		
RE-INSPECTION	FEE DUE? NO	YES	\$
IF	REQUIRED, RE-INSPECTION FEES M	UST BE PAID PRIOR TO SCI	HEDULING A RE-INSPECTION
	QUESTIONS? PLEASE CONTACT THE	INSPECTOR AT THE FOLL	OWING E-MAIL ADDRESS:
		iessica.contratto @co	o.kittitas.wa.us
• INS	SPECTION REQUEST LINE: <u>www.c</u> 411 N. Ruby Street, Suite 2, Ellenst		<del></del>
	· · · ·	-	